

ASN Wikibase Occurrence # 73914

Last updated: 19 October 2014

This information is added by users of ASN. Neither ASN nor the Flight Safety Foundation are responsible for the completeness or correctness of this information. If you feel this information is incomplete or incorrect, you can [submit corrected information](#).

Tweet 0

+1 0

Date: 25-JUL-1997

Time:



Type: [General Dynamics F-16C](#)

Owner/operator: Türk Hava Kuvvetleri (Turkish Air Force)


Registration: 91-0013

C/n / msn: TAI/4R-93

Fatalities: Fatalities: 0 / Occupants: 1

Other fatalities: 0

Airplane damage: Written off (damaged beyond repair)

Location: Kutahya province -  [Turkey](#)

Phase:

Nature: Military

Departure airport: Eskisehir AB

Destination airport:

Narrative:


Crashed. Pilot ejected.

Sources:

Scramble

Flight International 23-29 September 1998, p43

Related books



## Revision history:

Date/time	Contributor	Updates
11-Apr-2010 12:05	ChadSWA737	Added
11-Apr-2010 12:07	harro	Updated [Aircraft type, Cn, Damage]
20-Apr-2012 16:15	Dr. John Smith	Updated [Location, Embed code, Narrative]
19-Sep-2014 18:19	TB	Updated [Date, Time, Aircraft type, Registration, Cn, Operator, Total fatalities, Location, Country, Phase, Nature, Departure airport, Destination airport, Source, Embed code, Damage, Narrative]
21-Sep-2014 19:10	TB	Updated [Registration, Cn]

Number of views: 877

Corrections or additions? ... [Edit this accident description](#)

- [Home](#)
- [Disclaimer](#)
- [Copyright](#)
- [Privacy](#)
- [Submit correction](#)
- 

- Unless otherwise stated: copyright © 1996-2014 Aviation Safety Network (ASN)